

Date :

## **Hyundai Granby Estrie**

1165 Rue Principale Granby J2J 0M3

1 450 378-4666

## Make / Model Honda Civic Coupe EX TOIT ... Year Mileage indicated / actual\* 2014 120,691 km Transmission Drive Type FWD Engine Fuel Type 4 cyl. / 1.8 liters unleaded Serial number Stock number F2129



SALE PRICE

## **EQUIPMENTS**

Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power steering, Power windows, Adjustable steering wheel, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Intermittent wipers, Two-toned paint, CD player, MP3 Player, Bucket seats, Reverse camera, Variable speed intermittent wipers, Climate control, Driver vanity mirror, Passenger vanity mirror, Pass-Through rear seat, Rear head air bag, Front floor mats, Brake assist, Auxiliary audio input, Keyless entry, Auto-on headlights, Keyless start, Remote trunk release, Audio steering controls

\$11,997

Plus tax.

## Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for :

The dealer will supply upon request the name and phone number of the last owner.

	I	
	Category	
Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:	As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:	
Legal warranty : C - 1 month - 1700 KM		
	A 6 months or B 3 month 5 000 km	hs or C 1 month or 1 700 km
	D Good working E No warranty	
Repairs done and mechanical verification certificate		Comments
The following repairs have been done on this vehicle since the dealer's possession.		
If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.		
Optional repairs		
The following defects have been noted on this vehicle and can be repaired at the cost mentioned below:		

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :

\_ auto**Expert**...

7410323

Sticker #: