

Date:

Hyundai Granby Estrie

1165 Rue Principale Granby **J2J 0M3**

1 450 378-4666

Make / Model

Try dridar Elantia SE 67 tivi 107 to 5	
Year	Mileage indicated / actual*
2017	33,143 km
Transmission	Drive Type
automatic	FWD
Engine	Fuel Type
4 cyl. / 2 liters	unleaded
Serial number	Stock number
	F2154



SALE PRICE

EQUIPMENTS

Air conditioning, Cruise control, Heated mirrors, Power Mirrors, Power steering, Power windows, Adjustable steering wheel, Heated steering, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction control, Intermittent wipers, Two-toned paint, MP3 Player, Satellite radio, Bucket seats, Reverse camera, Variable speed intermittent wipers, Child safety locks, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Pass-Through rear seat, Rear head air bag, Front floor mats, Brake assist, Auxiliary audio input, Keyless entry, Auto-on headlights, Remote trunk release, Audio steering controls

\$16,4

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for:

The dealer will supply upon request the name and phone number of the last owner.

Category As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below: Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a: Legal warranty: C - 1 month - 1700 KM A 6 months or 10 000 km 3 months or 5 000 km 1 month or 1 700 km вΓ Good working (subject to 37, 38 L.P.C.) **Comments** Repairs done and mechanical verification certificate The following repairs have been done on this vehicle since the dealer's possession. If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code. **Optional repairs** The following defects have been noted on this vehicle and can be repaired at the cost mentioned below:

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Signature :



Sticker #: 7410347